User:

Monday, 6/5/2006 7:46:45 AM

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 27357

Estimate Number

: 10323

P.O. Number This Issue

Prsht Rev.

First Issue

Previous Run

NA

: 6/5/2006

: NIA

: 26661

: MACHINED PARTS

Part Number

Due Date

Drawing Name

: K10008

Drawing Number

: D2432 REV F3

: BEARPAW KIT (19"X24")

: N/A Project Number

Drawing Revision : F3

Material

:NA : 6/24/2006

Qty:

10 Um:

Each

Written By

Checked & Approved By

Comment

S.O. No. : NIA

Blank size changed KJ/JLM

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Photocopy bluefile:

K10008

D206-559-013

D350-578-011

D427-659-011

D315-670-011

and create labels per PPP K10008

CHG006(Bag Bluefiles separately)

UHMW 1" Black



Comment: Qty.:

MUHMWB10

6.8250 sf(s)/Unit Total: 68.2500 sf(s)

blank: 19.500" x 24.00" x 1.00" thick (+0.030/-0.000) per DSK086-5

Material: Black UHMW 1"

(MUHMWB10)

Batch: M 100501

Note:(2) bearpaws for (1) Kit



3.0

2.0

HAAS1




Comment: HAAS CNC VERTICAL MACHINING #1

1-Inspect material for defects or damage prior to machining

2-Machine as per Folio and Dwg D2432 Identify as D2432F

3-Deburr



10

Dart Aerospace Ltd

W/O:			٧	VORK ORDER C	HANGES				1	
DATE	STEP	PROC	CEDURE CH	IANGE		Ву	Date	Qty	Approval Mfg / Design Mgr	Approva QC Inspector
									1	
<u> </u>									1	
									ı	
NCR:		W	ORK OR	DER NON-CONF	ORMANC	E (NCR)			
		Decembries of NC		Corrective Actio	n Section B		16. 15.			
DATE	STEP	Description of NC Section A	Initial Design Mgr	Action Desc Design Mo	ription	Sign & Date	Verific Section		Approval Design Mgr	Approval QC Inspector
	!									-
								,		
Part No):	PAR #:	Fault Categ	ory:	NCR: Ye	s No	DQA:	ı		
NOTE: D	ate & initia	al all entries			O.	A: N/C CId	osed.		Date:	

H:\forms\Quality Assurance\approved forms\NCRWO revC

Date: Monday, 6/5/2006 7:46:45 AM User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X24") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10008 Job Number: 27357 Job Number: Description: Seq. #: Machine Or Operation: INSPECT PARTS AS THEY COME OFF MACHINE QC2 - - 4.0 Comment: INSPECT PARTS AS THEY COME OFF MACHINE 10 SECOND CHECK QC8 5.0 Comment: SECOND CHECK PACKAGING RESOURCE #1 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Pick Packing Kit D2182B050 Rubber Cushion 7.0 Comment: Qty.: 6.0000 Each(s)/Unit Total: 60.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch 6 D2182B050 Rubber Cushion 8.0 D2274 Comment: Qty.: 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Pick: Packing Kit B26078 3MC B26500 117MC Qty Part Number Description Batch 12 D2274 Radius Block Bearpaw 327357 2 D2432F(ref only) 9.0 D2438 Clamp Comment: Qty.: 6.0000 Each(s)/Unit Total: 60.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch Clamp <u>B25611</u> 6 D2438

Dart Aerospace Ltd

W/O:		,	WO	RK ORDER CHA	NGES					
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
			-						<u> </u>	
								:		
			WORK ORDE	D NON CONFO		- (1100)			<u>'</u>	
NCR:	T		WORK ORDE	R NON-CONFOR		= (NCR) . 			
DATE	STEP	Description of NC Section A	Initial Design Mgr	Corrective Action S Action Description Design Mgr		Sign & Date	Verifica Sectio		Approval Design Mgr	Approval QC Inspector
									 - -	
									1	
										-
				· · · · · · · · · · · · · · · · · · ·						
Part No):	PAR #:	Fault Category	:	NCR: Yes	s No I	DQA:	!	Date:	
NOTE: D	ate & initia	al all entries			QA	: N/C Clo	sed:	ï	Date:	1200

H:\forms\Quality Assurance\approved forms\NCRWO revC

Monday, 6/5/2006 7:46:45 AM Date: User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X24") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10008 Job Number: 27357 Job Number: Seq. #: Description: Machine Or Operation: Washer D2529 10.0 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch
12 D2529 Washer 3 6455 D2732050 Rubber Cushion 11.0 6.0000 Each(s)/Unit Total: 60.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch
6 D2732-050 Rubber Cushion 326972 AN415A 12.0 Comment: Qty.: 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Pick: Packing Kit

Qty Part Number Description Batch

ANA-15A Bolt M 90 85 AN417A 13.0 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch
12 AN4-17A Bolt 1997 AN960JD416 Washer 14.0

Comment: Qty.: 24.0000 Each(s)/Unit Total: 240.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

Washer M100575 24 AN960JD416

W/O:		WORK ORDER CI	ANGES			İ	
DATE	STEP	. PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
						1	
						1	
						1	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC	of NC Corrective Action Section B				Ammunual	T			
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector			
							!				
							1				
		10 m 17 M 10	·				ı				
							!				

Part No:	PAR #:	Fault Category: N	NCR:	Yes No DQA:	Date: 06/06/2
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Date: Monday, 6/5/2006 7:46:46 AM User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X24") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10008 Job Number: 27357 Job Number: Description: Seq. #: **Machine Or Operation:** Nut MS21042L4 Comment: Qty.: 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch 12 MS21042L4 Nut (or -4) INSPECT 100% KITS FOR COMPLETENESS QC4 16.0 Comment: INSPECT 100% KITS FOR COMPLETENESS PACKAGING RESOURCE #1 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPPK10008 Location: 18.0 DC 1 d6.06 23 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

Dart A	erospa	ce Ltd						İ	
W/O:			WC	RK ORDER CHANGES	3				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
								Ţ	
								!	
			•						
								1 .	
NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCF	5)		:	
HOIX.	· ,					- ,			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section B Action Description	Sign 8		ication Approva		Approval QC Inspector
		Section A	Design Mgr	Design Mgr	Date		ion C	Design Mgr	QC Inspector
								1	
								i	
								!	
								I I	
	1				į	1			

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:		Date:	
NOTE: Date & initial all entries		•		QA: I	N/C C	losed: _	· · · · · · · · · · · · · · · · · · ·	Date: _	

DART AEROSPACE LTD	Work Order:	27357
Description: Bearpaw	Part Number:	D2432
Inspection Dwg: D2432 Rev: F3		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Ins Draw	pection Sheet ving Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Α	0.063 x 45°	+0.030/-0.010	,063 445	3			
В	5.500	+/-0.030	5.500"				
С	0.200	+/-0.030	1985"	V			
D	0.25 x 45°	+/-0.030	,240 X45				
E	R0.250	+/-0.030	RO,250	0			
F	0.250	+/-0.010	, 253"	1			
G	0.625	+/-0.030	,630"	V			
Н	0.375	+/-0.010	378"				
ı	0.950	+0.030/0.010	.952"				
J	19.000	+/-0.030	19,000"	V			
К	3.14	+/-0.030	3.120"				
L	3.28	+/-0.030	3.30"	1/			
М	Ø0.260	+0.005/-0.000	\$,260'	V			
N	Ø0.93	+/-0.030	Ø ,930°	V			
0	0.30	+0.030/-0.000	3.15	V,			
Р	23.750	+/-0.030	23,750"	0,			
Q	7.375	+/-0.030	7.377	V			
R(4.250	+/-0.010	4 254"	V_{c}			
(s)	2:000	9 +/-0.030	1 695	V	-		
M	9.000	50°+/-0.010	9.005	V			
) U	9.000	+/-0.010	4.000				
·V	0.375	+/-0.010	385				
				$\overline{\nu}$			
				·			
							·

Measured by: J.F.

Date: 06/06/18

Audited by: 86

Date: 06.06.18


Prototype Approval: N/A

Date:

Rev	Date	Change		Revised by	Approved
Α	04.01.09	New Issue	P/O K10008/D206-559-015	KJ/RFC	·
		<u> </u>	· · · · · · · · · · · · · · · · · · ·		



DESIG	E	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHEC	KED _A /	APPROVED	DRAWING NO. RE	V. F
P	1 1 11	1 W	D2432 SHEET 1 0)F 2
DATE	<u></u>		TITLE	ALE
98.0	5.12		BEARPAW	1:6
 Α		95.10.31	NEW ISSUE	
В		96.01.24	RE-DESIGN	
С		96.03.26	CHANGE BORE AND C'BORE DEPTH	
D		96.06.04	MOVE SLOT	





Copyright 1995 by DART AEROSPACE LTD






DESIGN	DRAWN BY		OSPACE LTD ontario, canada
CHECKED	APPRO ED	DRAWING NO.	REV. F
NW .	(4)	D2432	SHEET 2 OF 2
DATE		TITLE	SCALE
98.05.12		BEARPAW	1:4







SECTION C-C

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE